

www.fsaservice.com/forms/warranty.pdf

[How was your experience with Full Spectrum?](#)



LOCATION		SITE		BILL TO:	
City of Scottsdale, Police Department 7601 East McKellips Road, Scottsdale, AZ 85257 United States Mr. Allan Kosecki, pkosecki@scottsdaleaz.gov				Customer	
Service Rep: Hong, Ryan		Service Type: PM		Quality Level: Standard	
Billing Type: Non-Billable		Payment Method: Service Contract		PO#: N/A	
System ID	Manufacturer	Model	Serial#		
GC w/ HS	Agilent	G3440A	CN14160045		
Additional Instruments					
PROBLEM DESCRIPTION:					
Agilent GC/Headspace Annual Preventative Maintenance.					
WORK PERFORMED:					
Cleaned dust off instruments. Replaced the 7697 Headspace 1 mL sample loop and sampling needle. Performed the system pressure and decay test. Pressure and decay test passed. Performed the tray offset calibration. Checked front and back FID flows. Confirmed the FID signals were less than 10. The system is operational and turned over to the client for use.					

FSA Part# (Inventory)	Description (manual)	Qty	Price Each	Total
AG-7697-1010	Agilent 7697A Sample probe, deactivated SN1030	1	\$499.00	\$499.00
AG-7697-6005	Sample loop, headspace, 1.00 mL, inert	1	\$458.00	\$458.00
GCHS-PM-LABOR	GC Headspace PM Labor	1	\$684.00	\$684.00

Parts Total: \$1641.00

HOURS	RATE	TOTAL	
Labor Hours: 2.0	Labor Rate: \$0	Labor Total:	\$0
Travel Hours: 2.0	Travel Rate: \$0	Travel Total:	\$0
	Extended Travel: \$0	Misc. S&H:	\$0.00
	NOT AN INVOICE, TAXES NOT INCLUDED	Total Labor:	\$0
~i:72:100~		Report Total:	\$1,641.00
		Credit Amount:	\$1641.00
		Balance Due:	\$0.00