



FSA Ticket # 42562  
 8/15/2022  
 Workorder # 34445  
 Region: ~204~  
 Vendor Ref #

[www.fsaservice.com/forms/warranty.pdf](http://www.fsaservice.com/forms/warranty.pdf)

[How likely are you to recommend Full Spectrum?](#)



<b>LOCATION</b>		<b>SITE</b>	<b>BILL TO:</b>	
City of Scottsdale, Police Department 7601 East McKellips Road, Scottsdale, AZ 85257 United States Kris Cano, kcano@scottsdaleaz.gov			Customer	
Service Rep: Iribe, Victor		Service Type: PM		Quality Level: Standard
Billing Type: Non-Billable		Payment Method: Service Contract		PO#: N/A
System ID	Manufacturer	Model		Serial#
GC w/ HS	Agilent	G3440A		CN14160045
Additional Instruments				
<b>PROBLEM DESCRIPTION:</b>				
PM				
<b>WORK PERFORMED:</b>				
Replaced sample probe and sample loop in 7697A headspace, and performed leak test; leak test passed. Removed front and back FID, and cleaned castle assembly. Then, both Jets and collectors were removed and cleaner per FSG protocol. The FIDs were re-assembled and re-installed. After flames were ignited, the customer ran their standards, and results were within their passing criteria. System was released back to customer for use.				

FSA Part# (Inventory)	Description (manual)	Qty	Price Each	Total
	Sample Loop, Headspace, 1.00 mL	1	\$456.50	\$456.50
	Agilent 7697A Sample Probe, Deactivate	1	\$480.24	\$480.24

Parts Total: \$936.74

HOURS	RATE	TOTAL	
Labor Hours: 6.0	Labor Rate: \$376	Labor Total:	\$2256
Travel Hours: 1.0	Travel Rate: \$376	Travel Total:	\$376
	Extended Travel: \$0	Misc. S&H:	\$0.00
	<b><u>NOT AN INVOICE, TAXES NOT INCLUDED</u></b>	Total Labor:	\$2632
~i:72:100~		Report Total:	\$3,568.74
		Credit Amount:	\$3568.74
		<b>Balance Due:</b>	<b>\$0.00</b>

23332 Mill Creek, suite 205, Laguna Hills, CA 92653 \* 800-795-6357 \* FAX: 925-485-9018