

An Integral Part of Your Company

FULL SPECTRUM
ANALYTICS INC.

FSA Ticket # 7,331
Workorder # 7209
Region: F4
Vendor Ref #

12/12/2017

www.fsaservice.com/forms/Warranty.pdf

SITE LOCATION		BILL TO:	
City of Scottsdale, Police Department 7601 East McKellips Road, Scottsdale, AZ 85257 Mr. Allan Kosecki, pkosecki@scottsdaleaz.gov		Full Spectrum	
Service Rep: Galvez, Joe	Service Type: Repair	Quality Level: Standard	
Billing Type: Non-Billable	Payment Method: Service Contract	PO#: N/A	
System ID	Manufacturer	Model	Serial#
GC w/ HS			
Additional Instruments	Agilent 7890 GC S/N US14173023		
PROBLEM DESCRIPTION:			
1 of 2 FIDs on the GC has an abnormally high signal.			
WORK PERFORMED:			
Observed a normal reading on one FID and an extremely high signal on the other. Disassembled the FID detector. Cleaned the FID jet and collector. Re-assembled the detector and repositioned the potentiometer. Powered on the instrument. Signal was significantly lower and continued to decrease as the system heated to their respective set points. System is operating properly.			

Parts Total:

HOURS	RATE	TOTAL	
Labor Hours: 2.0	Labor Rate: \$300.00	Labor Total:	\$600.00
Travel Hours: 2.0	Travel Rate: \$300.00	Travel Total:	\$600.00
	Extended Travel: \$0.00	Misc. S&H:	\$0.00
	NOT AN INVOICE, TAXES NOT INCLUDED	Total Labor:	\$1,200.00
		Report Total:	\$1,200.00
		Credit Amount:	\$1,200.00
		Balance Due:	\$0.00

1252 Quarry Lane * Pleasanton * CA 94566 * 800-795-6357 * FAX: 925-485-9018