



ARIZONA DEPARTMENT OF PUBLIC SAFETY

INTOXILYZER MAINTENANCE REPORT

CR NO. I800018790007

Page 1 of 1

AGENCY Scottsdale Police Department
Scottsdale, AZ 85251
OFFICER JUDD, #1232
DATE November 06, 2019



INSTRUMENT

80001879

INSTRUMENT LOCATION

Scottsdale Police Department

MAINTENANCE REQUESTED

Repair and Preventative Maintenance

MAINTENANCE PERFORMED

Parts Replaced:

Breath Hose, Source

Preventative Maintenance Performed:

Inspection, Calibration, Verification, Adjustment

A handwritten signature in black ink, appearing to read "Joseph M Slowinski".

JOSEPH M SLOWINSKI, #6101, Electronics Technician
Central Regional Crime Laboratory
2102 W. Encanto Blvd., Phoenix, AZ 85009
602-223-2159 jslowinski@azdps.gov



ARIZONA DEPARTMENT OF PUBLIC SAFETY

INTOXILYZER MAINTENANCE REPORT

CR NO. I800014640007

Page 1 of 1

AGENCY Scottsdale Police Department
 Scottsdale, AZ 85251
OFFICER JUDD, #1232
DATE November 05, 2019



INSTRUMENT

80001464

INSTRUMENT LOCATION

Scottsdale Police Department

MAINTENANCE REQUESTED

Repair and Preventative Maintenance

MAINTENANCE PERFORMED

Parts Replaced:

Breath Hose, End Block, Source

Preventative Maintenance Performed:

Inspection, Calibration, Verification, Adjustment

David K. Worthen

DAVID K. WORTHEN, #4871, Forensic Scientist
Central Regional Crime Laboratory
2102 W. Encanto Blvd., Phoenix, AZ 85009
602-223-2415 dworthen@azdps.gov