

An Integral Part of Your Company

**FULL SPECTRUM**  
ANALYTICS INC.

FSA Ticket # 5,379  
Workorder # 5296  
Region: F4  
Vendor Ref #

[www.fsaservice.com/forms/Warranty.pdf](http://www.fsaservice.com/forms/Warranty.pdf)

<b>SITE LOCATION</b>		<b>BILL TO:</b>	
City of Scottsdale, Police Department Mr. Allan Kosecki, pkosecki@scottsdaleaz.gov 7601 East McKellips Road, Scottsdale, AZ 85257		Full Spectrum	
Service Rep: Galvez, Joe	Service Type: PM	Quality Level: Standard	
Billing Type: Non-Billable	Payment Method: Service Contract	PO#:	
System ID	Manufacturer	Model	Serial#
GC w/ HS			
Additional Instruments	7697A Headspace S/N CN14160045		
<b>PROBLEM DESCRIPTION:</b>			
7697 Headspace Annual Preventative Maintenance			
<b>WORK PERFORMED:</b>			
Turned off H2 carrier gas and lowered the temperature to the needle and valve. Changed the headspace sample loop and sampling needle. Reassembled the unit and turned the carrier gas back on. Checked for any leaks and system was able to maintain pressure. Ran a test sample. System is operating properly.			

FSA Part# (Inventory)	Description (manual)	Qty	Price Each	Total
	7697 Sample Loop (1mL)	1	\$432.00	\$432.00
	7697 Sample Probe	1	\$497.00	\$497.00

Parts Total: \$929.00

Onsite Date	Start Time	End Time	Break Hours	Onsite Hours
8/7/2017	10:00 am	12:00 pm		2.0

Total Onsite: 2.0

HOURS	RATE	TOTAL	
Labor Hours: 2.0	Labor Rate: \$300.00	Labor Total:	\$600.00
Travel Hours: 2.0	Travel Rate: \$300.00	Travel Total:	\$600.00
	Extended Travel: \$0.00	Misc. S&H:	\$0.00
	<b>NOT AN INVOICE, TAXES NOT INCLUDED</b>	Total Labor:	\$1,200.00
		Report Total:	\$2,129.00
		Credit Amount:	\$2,129.00
		<b>Balance Due:</b>	<b>\$0.00</b>

1252 Quarry Lane \* Pleasanton \* CA 94566 \* 800-795-6357 \* FAX: 925-485-9018